



## Survey Report

NO.: ASZ08050601V

Date: May 14, 2008

Page 1 of 6

**Customer:** YISURE INDUSTRY AND TRADE CO.,LTD

**Address:** No.218 Cangchu Road, Jiangbei District Ningbo Zhejiang, P.R.China

**Report on the submitted sample said to be**

**Sample name:** PIZZADOME

**Model:** 6201

**Item/Lot No.:** /

**Material:** /

**Buyer:** /

**Supplier:** /

**Manufacturer:** /

**Reports received date:** May 05, 2008

**Requisition:** To combine the test reports for the submitted sample

**Conclusion:** All reports as specified by client, determine the Lead, Cadmium, Mercury, Hexavalent Chromium and/ or PBB & PBDE content in the submitted samples which are restricted in Directive 2002/95/EC (RoHS).

\*\*\*\*\*FOR FURTHER DETAILS, PLEASE REFER TO THE FOLLOWING PAGE (S)\*\*\*\*\*

**Signed for AOV Ltd.**

Written by

Inspected by

Approved by

This Test Report is issued by the Company subject to its Conditions of Issuance of Test Report printed overleaf or attached. The results shown in this Test Report refer only to the sample(s) tested unless otherwise stated and such sample(s) are retained for 30days only. This Test Report shall not be reproduced expected in full, without written approval of the Company.

**AOV Testing Technology Co. Ltd** 深圳市安姆特测试技术有限公司

Address: AOV Building, Xueyuan Road East, University City, Shenzhen (Tanglang Village, Xili Town, Nanshan District)

深圳市南山区西丽大学城学苑大道东 (西丽镇塘朗村) 安姆特大厦

Tel: +86 (0) 755-8600 8000 Fax: +86 (0) 755-8600 8282 Http: //www.aovt.com



# Survey Report

NO.: ASZ08050601V

Date: May 14, 2008

Page 2 of 6

## Test Results:

ITEM	PART NO.	COMPONENT DESCRIPTION	TEST SAMPLE	TEST LAB	REPORT NO. ISSUED DATE	TEST DATA (ppm)
1	1-1	Heat tube A	Argentate	PTS	NB2008012106-1	Cd: <2 Pb: <2 Hg: <2 Cr <sup>6+</sup> : <2
	1-2	Heat tube B				
2	2-1	Indicator light	Transparent plastic part	SGS	SH8000614/CHEM	Cd: ND Pb: ND Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
	2-2		Silvery metal pin part			Cd: ND Pb: ND Hg: ND Cr <sup>6+</sup> : ND
3	3	Hight temperature silicon rubber	White soft plastic with black printing	SGS	SH742542/CHEM	Cd: ND Pb: ND Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
4	4-1	Cermatic gasket	Silvery metal pin	SGS	SH730748/CHEM	Cd: ND Pb: 9 Hg: ND Cr <sup>6+</sup> : ND
	4-2	Round roof				
5	5-1	Roundens hold	Black oddment	SGS	SH7121558/CHEM	Cd: ND Pb: 4 Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
	5-2	Work shovel				
6	6-1	Warnning mark	Silvert metal	SGS	SH787880/CHEM	Cd: ND Pb: 7 Hg: ND Cr <sup>6+</sup> : ND
	6-2	Heating tray				
7	7	Pizza knife	Beige-grey plastic	SGS	SH796764/CHEM	Cd: ND Pb: 3

This Test Report is issued by the Company subject to its Conditions of Issuance of Test Report printed overleaf or attached. The results shown in this Test Report refer only to the sample(s) tested unless otherwise stated and such sample(s) are retained for 30days only. This Test Report shall not be reproduced expected in full, without written approval of the Company.

AOV Testing Technology Co. Ltd 深圳市安姆特测试技术有限公司

Address: AOV Building, Xueyuan Road East, University City, Shenzhen (Tanglang Village, Xili Town, Nanshan District)

深圳市南山区西丽大学城学苑大道东 (西丽镇塘朗村) 安姆特大厦

Tel: +86 (0) 755-8600 8000 Fax: +86 (0) 755-8600 8282 Http: //www.aovt.com



# Survey Report

NO.: ASZ08050601V

Date: May 14, 2008

Page 3 of 6

						Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
8	8	Feet	Rubber	SGS	SH8023507/CHEM	Cd: 9 Pb: 3 Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
9	9-1	Button	Silvery metal	SGS	SH7102893/CHEM	Cd: ND Pb: ND Hg: ND Cr <sup>6+</sup> : ND
	9-2	Middle ring				
	9-3	Cover				
	9-4	Work shovel				
	9-5	Fixing parts of heat tube				
	9-6	Press piece of heat tube				
10	10-1	Flat screw	Screw (plating zinc)	TUV NORD	TRHZPR0711026	Cd: ND Pb: 14 Hg: 5 Cr <sup>6+</sup> : ND
	10-2	Standard screw				
	10-3	Attack screw				
	10-4	Spring gasket				
	10-5	Flat gasket				
	10-6	Nut				
	10-7	Butterfly nut				
	10-8	Big dia flat gasket				
11	11-1	Earthing mark	White paper	SGS	SH763555/CHEM	Cd: ND Pb: ND Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
	11-2	Warning mark for plug				
	11-3	Warning mark for A1 plug				
	11-4	Label for bottom				
	11-5	Magnetism mark of oven				
	11-6	Bunch number				
	11-7	Instruction				
	11-8	Air bladder piece of round roof				
12	12-1	UL10 °C PVC Inlated	/	SGS	SH770405/CHEM	Cd: ND

This Test Report is issued by the Company subject to its Conditions of Issuance of Test Report printed overleaf or attached. The results shown in this Test Report refer only to the sample(s) tested unless otherwise stated and such sample(s) are retained for 30days only. This Test Report shall not be reproduced expected in full, without written approval of the Company.

AOV Testing Technology Co. Ltd 深圳市安姆特测试技术有限公司

Address: AOV Building, Xueyuan Road East, University City, Shenzhen (Tanglang Village, Xili Town, Nanshan District)

深圳市南山区西丽大学城学苑大道东 (西丽镇塘朗村) 安姆特大厦

Tel: +86 (0) 755-8600 8000 Fax: +86 (0) 755-8600 8282 Http: //www.aovt.com



# Survey Report

NO.: ASZ08050601V

Date: May 14, 2008

Page 4 of 6

		material				Pb: 5 Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
	12-2	Oxygen free bare copper wire	/	SGS	SH770405/CHEM	Cd: ND Pb: ND Hg: ND Cr <sup>6+</sup> : ND
	12-3-1	Black plastic jacket with white printing	/	SGS	SH770405/CHEM	Cd: ND Pb: 5 Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
	12-3-2	Brown plastic jacket	/	SGS	SH770405/CHEM	Cd: ND Pb: 6 Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
	12-3-3	Blue plastic jacket	/	SGS	SH770405/CHEM	Cd: ND Pb: 4 Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
	12-4	Qian Tou Inner rack	/	SGS	SH770405/CHEM	Cd: ND Pb: 267 Hg: ND Cr <sup>6+</sup> : ND
	12-5	Qian Tou rack	/	SGS	SH770405/CHEM	Cd: 95 Pb: ND Hg: ND Cr <sup>6+</sup> : ND
	12-6	Qian Tou Inner rack	/	SGS	SH770405/CHEM	Cd: ND Pb: 4 Hg: ND Cr <sup>6+</sup> : ND

This Test Report is issued by the Company subject to its Conditions of Issuance of Test Report printed overleaf or attached. The results shown in this Test Report refer only to the sample(s) tested unless otherwise stated and such sample(s) are retained for 30days only. This Test Report shall not be reproduced expected in full, without written approval of the Company.

AOV Testing Technology Co. Ltd 深圳市安姆特测试技术有限公司

Address: AOV Building, Xueyuan Road East, University City, Shenzhen (Tanglang Village, Xili Town, Nanshan District)

深圳市南山区西丽大学城学苑大道东 (西丽镇塘朗村) 安姆特大厦

Tel: +86 (0) 755-8600 8000 Fax: +86 (0) 755-8600 8282 Http: //www.aovt.com



## Survey Report

NO.: ASZ08050601V

Date: May 14, 2008

Page 5 of 6

	12-7-1	White plastic grains	/	SGS	SH770405/CHEM	Cd: ND Pb: ND Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
	12-7-2	Black plastic grains	/	SGS	SH770405/CHEM	Cd: ND Pb: 4 Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
	12-8	UL105°C PVC Insulated material	/	SGS	SH770405/CHEM	Cd: ND Pb: 5 Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
	12-9	UL105°C PVC Insulated material	/	SGS	SH770405/CHEM	Cd: ND Pb: 6 Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
13	13-1	Casing foam	PVC	TUV NORD	TRHZPR0711009	Cd: ND Pb: 13 Hg: 7 Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
	13-2	Out casing				
	13-3	Casing bag				
14	14-1	Dull white plastic	Electrical source wire pin	Intertek	SZHJ044972	Cd: ND Pb: ND Hg: ND Cr <sup>6+</sup> : ND PBBS: ND PBDES: ND
	14-2	White plastic				Cd: ND Pb: ND Hg: ND

This Test Report is issued by the Company subject to its Conditions of Issuance of Test Report printed overleaf or attached. The results shown in this Test Report refer only to the sample(s) tested unless otherwise stated and such sample(s) are retained for 30days only. This Test Report shall not be reproduced expected in full, without written approval of the Company.

AOV Testing Technology Co. Ltd 深圳市安姆特测试技术有限公司

Address: AOV Building, Xueyuan Road East, University City, Shenzhen (Tanglang Village, Xili Town, Nanshan District)

深圳市南山区西丽大学城学苑大道东 (西丽镇塘朗村) 安姆特大厦

Tel: +86 (0) 755-8600 8000 Fax: +86 (0) 755-8600 8282 Http: //www.aovt.com

## Survey Report

NO.: ASZ08050601V

Date: May 14, 2008

Page 6 of 6

						Cr <sup>6+</sup> : ND PBBs: ND PBDES: ND
--	--	--	--	--	--	--

### Note:

-N.D.= not detected (<2ppm)

-ppm=mg/kg

- Negative=Absence of Cr(VI)

-The sample description of this report is translated which is requested by customer. If there is divarication between English and Chinese descriptions, please refer to original reports

-Test results are from other testing organizations. AOV testing technology Co., Ltd has no liability to assume the verification of the authenticity of the above test reports results.

-Photograph is included.

### Photograph of Sample



PIZZADOME

\*\*\*End of Report \*\*\*

This Test Report is issued by the Company subject to its Conditions of Issuance of Test Report printed overleaf or attached. The results shown in this Test Report refer only to the sample(s) tested unless otherwise stated and such sample(s) are retained for 30days only. This Test Report shall not be reproduced expected in full, without written approval of the Company.

AOV Testing Technology Co. Ltd 深圳市安姆特测试技术有限公司

Address: AOV Building, Xueyuan Road East, University City, Shenzhen (Tanglang Village, Xili Town, Nanshan District)

深圳市南山区西丽大学城学苑大道东（西丽镇塘朗村）安姆特大厦

Tel: +86 (0) 755-8600 8000 Fax: +86 (0) 755-8600 8282 Http: //www.aovt.com